

2013-2015 ALTIMA; CVT DELAYED ENGAGEMENT WHEN SHIFTING INTO DRIVE OR REVERSE

- Pin toolbar
- Hide all annotations
- 🕒 View document properties

This bulletin has been amended. The PARTS INFORMATION section has been revised. No other changes have been made. Please discard all previous versions of this bulletin.