MK-4 & MK-5 Hard Drive Recovery Instructions

System recovery of your CONSULT MK-4/MK-5 to Windows 7

The system recovery will erase all the data on your hard drive. Do not restart or switch off your computer during this process.

Required Items:

CF-19 MK-4/MK-5 Recovery Disk (3 disc set) DVD/CD external drive (supplied with CONSULT kits)

Installation Procedure:

- 1. Connect the AC adapter to the PC
- 2. Connect a DVD/CD external drive to the PC's USB port
- 3. Turn the PC on, press [esc] while "Panasonic" boot screen is displayed and then the Boot menu is displayed
- 4. Place the disk 1 into the DVD/CD external drive
- 5. On the Boot menu select the CDR option and press [Enter]
- 6. At the confirmation message, press [Y]
- 7. On the Recovery options displayed select 'Reinstall Windows' and then click 'Next'

Recovery		X
Please select from following items.		
 Reinstall Windows. 		
C Erase the whole data on the Hard Disk for servurity.		
4		
C Run "System Recovery Options".		
	Next	Cancel

8. Screen with an Agreement is displayed; select 'yes, I agree to the provisions above and wish to continue!' and click 'Next'



9. On the reconfirm screen click 'Next'

Recovery		X
Please reconfirm.		
Reinstall Windows to the whole Hard Disk to f	factory default.	
	Next	Cancel

10. And then click 'Yes' on the Please reconfirm screen.



11. The installation will start (Disc #1 process will take approximately 80 minutes)

- 12. When the Disc #1 operation is complete, the installation will prompt to insert Disk #2
- 13. Remove Disc #1 and insert Disc #2 in the DVD drive (Disc #2 operation will take approximately 70 minutes)
- 14. When the Disc #2 operation is complete, the installation will prompt to insert Disk #3.
- 15. Remove Disc #2 and insert Disc #3 in the DVD drive (Disc #3 operation will take approximately 50 minutes)
- 16. When the recovery is finished successfully a message will be displayed.
- 17. Remove Disc #3 and disconnect the external drive from the PC.
- 18. Ensure AC adaptor is still connected to PC and boot up the PC to slide the power switch.
- 19. Select English 64bit (or preferred language 64bit)

English(32bit)	-
English(64bit)	
Arabic(32bit)	
Arabic(64bit)	
Bulgarian(32bit)	
Bulgarian(64bit)	-
Chinese-HongKong(32bit)	
Chinese-HongKong(64bit)	
Chinese-Simplified(32bit)	
Chinese-Simplified(64bit)	
Croatian(32bit)	
Croatian[64bit]	
Czech[32bit]	
Danich(32bit)	
Danish(54bit)	
Dutch (2014)	
LUITCH 17 DIT	

20. Click OK. Once the computer is turned off, reboot the PC by sliding the power switch.

Recovery	×
Ending process.	
Windows(R) install wizard will start after reboot.	
Click 'OK' turn off your computer.	
I	
	OK

This completes the reimage, please be sure to store your recovery disks in case a recovery is needed in the future.

You are now ready to install ASIST on this PC. ASIST Installation USB and ASIST installation instructions were included with your upgrade kit; please refer to ASIST installation instructions to install ASIST.